


43

1/8








FIG.2

FIG.3





5/8

FIG. 4a





FIG.5
 LONGITUDINAL AND TRANSVERSE CREEP-RUPTURE LIFE
 OF
 CANDIDATES AT 1800°F-27ksi VS GTD 111



7/8

FIG.6a

SHOWS SLIGHTLY IMPROVED 1400° F
CREEP-RUPTURE LIFE VS GTD 111 DS




FIG.6b

SHOWS INCREASED CREEP-RUPTURE
LIFE AT 1800° F VS GTD 111 DS




FIG. 7

